



Manufacturers of Spring Assisters & Motor Accessories

GRAYSTON ENGINEERING LIMITED
 115 Roebuck Road • Chessington • Surrey KT9 1JZ • UK
 Telephone: 020 8974 1122 Fax: 020 8974 2288

FORD SIERRA 82-93 21S05
 ex. Estate
 FORD GRANADA 85- 21S06

PARTS (x2)

- (1) auxiliary spring
- (2) smaller seat
- (3) larger rubber collar
- (4) smaller rubber collar
- (5) larger seat
- (6) washer with side-opening
- (7) rubber
- (8) upper seat with side-opening
- (9) dust cover

1. Remove rear shock absorbers.
2. a. plastic dust cover keep in hot water and push off.
 b. steel dust cover -see Fig. 2a- cut off approx. 1 cm from top, cut through loose tube lengthwise and remove it.
3. Measure the shock absorber body diameter:
 Fig. 1 ϕ 38,5 mm
 Fig. 2a,b see drawing
 Fig. 3 ϕ 40 mm
 Fig. 4 ϕ 43 mm

Fit parts as shown.

PLEASE NOTE:

Fig. 1 + 2b: The slots in the spring seats(2 + 5) to be fitted opposite each other.

4. Re-install shock absorbers.

